


FIG. 5



Gray Scale	Condition
0 - 3	Α
4 - 10	В
11 - 53	С
54 - 60	В
61 - 63	A

FIG. 6

FIG. 7

Condition	Addition/ Subtraction Amount
A	0
В	-2
С	-4
•	•

5/6 JA9-96-016

